

Oil Field Environmental Incident Summary

Incident: 20141019153325

Date/Time of Notice: 10/19/2014 15:33

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: ALBERT SKARI 35-26H

Field Name: SANDROCKS

Well File #: 24257

Date Incident: 10/18/2014

Time Incident: 11:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 100

Sec: 35

Qtr: SE SE

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3650 Feet

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	23	Barrels		
Brine						
Other			2	Barrels		

Description of Other Released Contaminant:

Fresh water standing in the dike from rain fall

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Upon discovery of the leak the pump was shut down and was repaired. Vacuum truck called to recover spilled fluid.

Wastes Disposal Location: Taken to Nygaard SWD

Agencies Involved:

Updates

Date: 10/24/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location pump leak, remained on location within the diking according to the report. NDIC retains oversight.